

Firmware Version: V4.7.0.10
Published: Mar 15, 2018

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL D-LINK OR ITS SUPPLIERS BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE D-LINK PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF D-LINK IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, D-LINK WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. D-LINK WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT D-LINK RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content:

Revision History and System Requirement: 2

New Features: 2

Problems Fixed: 2

Known Issues: 2

CLI Commands 2

Related Documentation: 3

Revision History and System Requirement:

FW Version	Date	Model	HW	MD5 CHECKSUM
V4.7.0.10	15-Mar-2018	DWL-6620APS	A1	EDC69A99E3D8D1BBF4936AB3BE6540CC

New Features:

Firmware Version	New Features
V4.7.0.10	The first release

Problems Fixed:

Firmware Version	Problems Fixed
V4.7.0.10	The first release

Known Issues:

Firmware Version	Issues
V4.7.0.10	1. When 802.11ac wireless clients associate with a DWL-6620APS in managed mode, the clients will be shown as 802.11n clients on the DWC-2000. 2. The DWL-6620APS won't be changed to Standalone mode once losing association with the controller. 3. When enabling Dynamic VLAN feature, the wireless client could not be assigned proper VLAN ID if not configure use_tunneled_reply = yes on the FreeRadius server.

CLI Commands

Command	Action
get managed-ap	Get information about switches that can discover and manage the AP.
get management	View the following information about the management interface on the AP: • VLAN ID • Interface name • Static IP address (if DHCP is not used) • Static subnet mask • IP address • Subnet mask

	• MAC address • DHCP status
get management dhcp-status	View the connection type.
set management dhcp-status on	Use DHCP as the connection type.
set management dhcp-status off	Use Static IP as the connection type.
get management static-ip	View the static IP address.
get management static-mask	View the subnet address.
get management vlan-id	View management VLAN ID.
set management vlan-id *1~4069*	Set management VLAN ID.
reboot	Reboot the system.
factory-reset	Return to factory default setting.
get system led	View system LED status. Status 1: Turned on. Status 0: Turn off.
set system led on set system led off save-running	Turn on system LED. Turn off all system LED. After setting command, need to type the command *save-running* to and then *reboot* to make the setting effective.

Related Documentation:

- DWL-X600AP_3610AP_8610AP_6610AP _6700AP_8710AP_x620AP_Unified_AP_Manual_v6.61.pdf